

## FUNCTION SETTINGS

### 1. To change & set BAUD Rating, Parity & Print Mode

Press [ON/OFF] to turn on the scale on. This display will show -----, As soon as you see -----, press [PRINT] and the display will show **b xxx BAU** value (BAUD Rate). Press [UNIT] to select 1200, 2400, 4800 or 9600.

Press [ZERO] to enter Parity mode, the display will show **P XXX PAR**. Press [UNIT] to select **odd, even or none** (**odd** stands for 7 data bits with odd parity, **even** stands for 7 data bits with even parity, **none** stands for 7 data bits without parity).

Press [ZERO] to enter Print mode. The display will show **n xxx Mod**. Press [UNIT] to select **ON, OFF, KEY or STB** (**OFF** stands for serial data output disabled, **KEY** stands for demand mode by pressing [PRINT], **STB** stands for automatic print when scale is stable and **ON** stands for continuous print. Press [ZERO] again to return to weighing mode.

### 2. To activate and deactivate weighing units

Press [ON/OFF] to turn on the scale on. The display will show digits and then -----, As soon as you see ----- press [UNIT] to enter unit selection mode. The display will show **ON X** (X stands for the units i.e. g or oz). Press [ZERO] to select an unit and press [UNIT] to select ON (to activate the selected unit) or OFF (to de-activate the selected unit). Press [ZERO] until you return to weighing mode.


### 2. To change & set the Zero, Tare, Overload & Back Light settings

Press [ON/OFF] to turn on the scale on. The display will show digits and then -----, As soon as you see ----- press [PCS]. Following the table below, use the [ZERO] button to enter each setting and [UNIT] button to change the value in each setting.

Setting (shown as it is seen on the display)	What setting you are changing	What you can choose from
<b>ZRD X.X</b>	Zero Track Value	0.0, 0.2, 0.4, 0.6, 0.8, 1.0, 1.5 & 2.0
<b>ZRT X.X</b>	Zero Track Time	0.5, 1.0, 1.5, 2.0, 2.5, 3.0, 3.5 & 4.0
<b>RZD X.X</b>	Zero Value	0.8, 1.8, 2.8 & 3.8
<b>FIL X</b>	Filter Range	0, 1, 2, 3, 4, 5, 6 & 7
<b>PZR XX</b>	Set percentage for zero range when the scale is first turned on	1, 2, 3, 4, 5, 8, 10 & 20
<b>TZR XX</b>	Set percentage of zero range	3, 4, 5 & 10
<b>TTR XXX</b>	Set percentage of tare range	50 or 100
<b>OUR XX</b>	Overload Protection Mode	2, 5, 10 9d
<b>b2 XX</b>	Activate or deactivate beep when buttons are pressed	ON or OFF
<b>ZT XX</b>	Unite tare & zero function	ON or OFF
<b>A XXX</b>	Auto-power off settings	3, 5, 10mins or OFF
<b>L XXX</b>	Back Light settings	AUTO, OFF or ON

# COMPACT SCALE/BALANCE

## INSTRUCTION MANUAL



# SAFETY PRECAUTIONS

All safety messages are identified by the following the words "WARNING" and "CAUTION". These words mean the following:

△WARNING	Important information to alert you to a situation that might cause serious injury and damage to your scale if instructions are not followed.
△CAUTION	Important information that tells how to prevent damage to equipment.

When using the scale/balance, the following safety precautions should always be followed.

### △ WARNING

**Use only the AC/DC mains adapter provided with the scale/balance. Other adapters may cause damage to the scale.**

**Do NOT use the mains adapter while batteries are fitted inside this scale. It will result in permanent damage to the circuit board.**

### △ CAUTION

Avoid installing the scale/balance in direct sunlight; this may cause discoloration or malfunctions.

Avoid overloading the scale; it could cause damage to the scale/balance.

Do not allow the scale to come into contact with water; it is not water-proof. If water comes in contact with the circuit board it will damage the scale/balance.

Avoid using the scale near anything that has electrically charged matter. Discharge the static electricity using an electrification prevention spray and spray on both sides of the weighing platform.

# SPECIFICATIONS

Model number	Capacity	Division
FHB -600	600g	0.01g/0.005g
FHB -3000	3000g	0.05g/0.1g
FHB -6000	6000g	0.1g/0.2g
Platter	120 x 135mm or 160 x 195mm	
Net/gross weight	1.8Kg	
Package	Standard carton: 36.5x26x16(cm <sup>3</sup> )	
Operating Temperature	0-40°C (32-104°F)	
Power source	AC/DC Adapter or Batteries	
	Adapter 10V/500mA	

## Parts Counting procedure

**1. Press [ON/OFF] to turn on the scale.**

Wait for "0" to appear on the display.

**2. Start the Count Procedure**

If necessary, press the [ZERO] key to set the display to "0".

**3. Press the [PCS] key to put the scale in parts counting mode, the display will show P=X X, press UNIT to select XX value (10, 20 ,50, 100) and place your sample on the platform of the scale/balance.**

**4. Press the [PCS] key, the display will show "XX pcs", then the scale will recall the sample size you selected and show the starting sample size on the display.**

**5. You can now remove the samples if you want to return the scale to 0 & start counting.**

**6. Press the [PCS] key to return to the weighing mode**

## CALIBRATION

### When to calibrate

Calibration may be required when it is initially installed or if the scale/balance is moved to a substantial distance. This is necessary because the weight of a mass in one location is not necessarily the same in another location due to gravity. Also, with time and use, mechanical deviations may occur.

### How to calibrate

1. Before entering calibration mode, **there is a switch key on the bottom of the scale. Turn on the switch key first** then press [ON/OFF] button on the front of the scale/balance to turn the power on and leave the scale/balance to warm up for 1 minute.

#### 2. Enter calibration mode

Press [ON/OFF] button to turn the power on. The display will show different digits and then "-----". As soon as you see "-----" press [ZERO] **twice**, the display will show "CAL." Press [ZERO] again, the display will show "**X0000** CAL"; **X** indicates the digit flashing on the display. Press [UNIT] key the flashing digit will move to the right. Press [PCS] key to increase the flashing digit. (*X is the calibration weight which can be set according to your requirements*).

#### 3. Calibration by the weight

When you have entered the weight you wish to carry out the calibration with, place the calibration weight/s onto the platform of the scale/balance. Then press [ZERO] key, the display returns to the weighting mode. Remove the calibration weight and calibration is now complete.


#### 4. Check the calibration has worked

Press [ON/OFF] to turn the scale/balance off. Then press [ON/OFF] to turn the scale/balance back on. Place the weight on the platform and check that the scale/balance is weighing correctly, if not, repeat steps 2-4.


## PARTS DESCRIPTION

### ▶ BACK

AC adaptor  
Socket



### ▶ FRONT



#### • Key pad function

1. **ON/OFF** key: Turn the power on or off.
2. **ZERO** key: For zero setting of the scale up to 4% of the scales capacity (i.e. for a 600g capacity 4% would be 24g)
3. **TARE** key: Press this button to deduct the weight on the display (useful for containers)
4. **PRINT** key: To print the displayed data.
5. **UNIT** key: Press this button to select different weighing units.
6. **PCS** key: For parts counting function.

### ▶ DISPLAY


Low battery indicator

Negative value indicator

weighing unit

TARE indicator

STABLE indicator  
Indicates when the  
reading is stable.



ZERO indicator


## PREPARATION

### 1. Installing batteries

#### Batteries

Battery  
compartment

switch power



6 AA Batteries

### 2. Setting up the scale/balance

#### △ CAUTION

Avoid installing the scale/balance in direct sunlight it may cause discoloration or malfunctions. Place your scale/balance on a firm weighing table so that the scale/balance is level. (The scale/balance will not perform accurately when it is not level.)

**Place the scale/balance on a firm surface that is flat and level for an accurate reading.**

## WEIGHING

### Before weighing

Turn the scale on and leave for 10 minutes to warm up before use

#### Error messages

Err-O: Overload

Err-Z: Zero tracks has been exceeded

Err- S: The scale is unstable

: Low battery

### Weighing procedures

#### 1.Press [ON/OFF] to turn on the balance.

When the scale/balance is turned on, all display segments appear on the LCD display for a few seconds and finally "0" will appear on the display.

#### 2.Select the weighing unit with [UNIT].

Press [UNIT] to select a weighing unit, e.g. g, ct, oz or dwt (there are 16 units to choose from)

#### 3.Start weighing

##### If you do not use a container for weighing

Check that the display is showing 0. If not, press [ZERO].

Place objects on the weighing platform to weigh.

When the reading becomes stable, the stable indicator is displayed.

##### If you use a container for weighing

Check that the display is showing 0. If not, press [ZERO].

Place an empty container on the platform.

Wait for the stability indicator to be displayed and press [TARE].

Place the objects to be weighed in the container.

When the reading becomes stable, the stable indicator is displayed.

## FEATURES

- User calibration
- Auto zero tracking
- Recharge
- Large LCD Display
- Stability indicator
- 1/120000 & 1/200000 division available
- Auto shut off (selectable)
- Auto backlight (selectable)
- g/ct/oz/..... conversion
- counting function